

## Information regarding Release

### **BAT Management System Version 10.34-RU1**

Copyright (c) 2002 – 2021 Hirschmann Automation and Control GmbH, Neckartenzlingen (Germany)  
Hirschmann Automation and Control GmbH takes no responsibility or warranty for Software not developed or manufactured by Hirschmann Automation and Control GmbH, especially with regard to shareware and other third-party software.

Hirschmann Automation and Control GmbH  
Stuttgarter Straße 45-51  
72654 Neckartenzlingen  
Germany

Internet: <http://www.beldensolutions.com>

2021-11-15

## **Table of Contents**

<b>1. Preface.....</b>	<b>3</b>
Note .....	3
<b>2. Known Issues .....</b>	<b>3</b>
<b>3. Overview on new features as of version LANtools 10.34-RU1 .....</b>	<b>4</b>
LANconfig (Build 0009) .....	4
<b>4. Overview on new features as of version LANtools 10.34 .....</b>	<b>5</b>
LANconfig (Build 0007) .....	5
LANmonitor (Build 0002) .....	5

## **1. Preface**

This software consisting of LANconfig and LANmonitor, serves for the administration of all BAT WLAN Access Points and BAT-Controllers.

### **Note**

The BAT Management System supports the following operating systems Windows 7, Windows 8, Windows 10.

## **2. Known Issues**

When using the Spectral Scan functionality along with the internal web browser it is possible that the internal web browser is closed in LANmonitor. Alternatively, an external web browser can be used.

Using SNMPv3 as access protocol in LANmonitor takes a longer time than using SNMPv1 or SNMPv2.

The transmission modes regarding the FCC-4.9GHz are displayed incorrect in LANconfig and LANmonitor.

### 3. Overview on new features as of version LANtools 10.34-RU1

#### LANconfig (Build 0009)

- **Support for HiLCOS-10.34.5402-RU1.**
- **Bugfixes**

The configuration of FCC-4.9GHz feature was not functional using LANconfig. As a consequence, an incorrect and different configuration state might have been presented by LANconfig than is actually present on the device. This issue has been resolved.



The **Hirschmann™** BAT Operating System

#### **4. Overview on new features as of version LANtools 10.34**

##### **LANconfig (Build 0007)**

- Initial version to support HiLCOS-10.34.5250-Rel

##### **LANmonitor (Build 0002)**

- Initial version to support HiLCOS-10.34.5250-Rel