

Information regarding Release

BAT Management System Version 10.32

Copyright (c) 2002 – 2020 Hirschmann Automation and Control GmbH, Neckartenzlingen (Germany)
Hirschmann Automation and Control GmbH takes no responsibility or warranty for Software not developed or manufactured by Hirschmann Automation and Control GmbH, especially with regard to shareware and other third-party software.

Hirschmann Automation and Control GmbH
Stuttgarter Straße 45-51
72654 Neckartenzlingen
Germany

Internet: <http://www.beldensolutions.com>

2020-12-17

Table of Contents

1. Preface.....	3
Note	3
2. Known Issues	3
3. Overview on new features as of version LANtools 10.32	4
LANconfig (Build 0005)	4
LANmonitor (Build 0003)	4

1. Preface

This software consisting of LANconfig and LANmonitor, serves for the administration of all BAT WLAN Access Points and BAT-Controllers.

Note

The BAT Management System supports the following operating systems Windows 7, Windows 8, Windows 10.

2. Known Issues

When using the Spectral Scan functionality along with the internal web browser it is possible that the internal web browser is closed in LANmonitor. Alternatively an external web browser can be used.

Using SNMPv3 as access protocol in LANmonitor takes a longer time than using SNMPv1 or SNMPv2.

The configuration of FCC-4.9GHz feature is not functional using LANconfig. As a consequence LANconfig might show an incorrect and different configuration state than it is actually present on the device.

The transmission modes regarding the FCC-4.9GHz are displayed incorrect in LANconfig and LANmonitor.

3. Overview on new features as of version LANtools 10.32

LANconfig (Build 0005)

- Support of HiLCOS-10.32.5410-Rel
- Support of new BAT-Controller Virtual devices

LANmonitor (Build 0003)

- Support of HiLCOS-10.32.5410-Rel