

Information regarding Release

BAT Management System Version 10.12

Copyright (c) 2002 – 2019 Hirschmann Automation and Control GmbH, Neckartenzlingen (Germany)
Hirschmann Automation and Control GmbH takes no responsibility or warranty for Software not developed or manufactured by Hirschmann Automation and Control GmbH, especially with regard to shareware and other third-party software.

Hirschmann Automation and Control GmbH
Stuttgarter Straße 45-51
72654 Neckartenzlingen
Germany

Internet: <http://www.beldensolutions.com>

2019-07-19

Table of Contents

1. Preface.....	2
Note	2
2. Known Issues	2
3. Overview on new features as of version LANtools 10.12 RU1	3
LANconfig (Build 0006)	3
LANmonitor (Build 0001)	3
4. Overview on new features as of version LANtools 10.12	4
LANconfig (Build 0004)	4
LANmonitor (Build 0001)	4

1. Preface

This software consisting of LANconfig and LANmonitor, serves for the administration of all BAT WLAN Access Points.

Note

The BAT Management System supports the following operating systems Windows 7, Windows 8, Windows 10.

2. Known Issues

When using the Spectral Scan functionality along with the internal web browser it is possible that the internal web browser is finished in LANmonitor. Alternatively an external web browser can be used.



The **Hirschmann™** BAT Operating System

3. Overview on new features as of version LANtools 10.12 RU1

LANconfig (Build 0006)

- Support of HiLCOS-10.12.5500 RU1

LANmonitor (Build 0001)

- Support of HiLCOS-10.12.5500 RU1



The **Hirschmann™** BAT Operating System

4. Overview on new features as of version LANtools 10.12

LANconfig (Build 0004)

- Support of HiLCOS-10.12.5500 RU1
- Bugfix LANconfig operates on Windows 10

LANmonitor (Build 0001)

- Support of HiLCOS-10.12.5500 RU1